

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:			
Company	Gary E. Gray Resident Agent		
OGM	Karl Houskeeper Environmental Scientist III		

Inspection Report

Permit Number:	C0150032		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, January 11, 2005		
Start Date/Time:	1/11/2005 9:00:00 AM		
End Date/Time:	1/11/2005 12:00:00 PM		
Last Inspection:	Wednesday, December 07, 2005		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Rain valley Temp 34 F, Snow mountain Temp 30 F

InspectionID Report Number: 505

Accepted by: pgrubaug 1/23/2005

Permitee: **GENWAL RESOURCES INC**Operator: **GENWAL RESOURCES INC**Site: **CRANDALL CANYON MINE**

Address: PO BOX 1077, PRICE UT 84501

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: **ACTIVE**

	Current Acreages	Mineral Ownership	Types of Operations
--	------------------	-------------------	---------------------

5,195.80	Total Permitted	✓ Federal	Underground
10.70	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	☐ Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending Amendments: South Crandall Lease Revision Task ID #2084 was received by the Division on 12/9/04 and is currently under review.

Inspector's Signature

Date

Tuesday, January 11, 2005

Karl Houskeeper, Environmental Scientist III Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 11, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		~		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 11, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

South Crandall Lease Revision Task ID #2084 was received by the Division on 12/9/04 and is currently under review.

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

All of the diversions on the mine site are snow covered. The diversion above the oil storage area has snow in the diversion from snow removal activities. The operator is still in the process of removing snow, including removal of snow that has entered the diversion.